



Transmission Assembly



Rear Assembly



*Requires 5117 or 5117A ball bearing for installation.

[illegible]

The logo for Stampede 4x4 VXL. The word "STAMPEDE" is in a large, bold, italicized sans-serif font with a thick black outline. Below it, "4x4" is in a very large, bold, italicized sans-serif font, also with a thick black outline. To the right of "4x4", "VXL" is in a smaller, bold, italicized sans-serif font with a thick black outline. Below "4x4 VXL", the words "BRUSHLESS" and "ELECTRIC" are written in a smaller, plain sans-serif font.

Front Assembly


REV 240521-R02
See Parts List for a complete
listing of optional accessories.

Specifications on this page are subject to change without notice. Every attempt has been made to ensure the accuracy of this drawing; however, Traxxas cannot be held responsible for typographical or other errors.

Driveshafts


Front Driveshaft Assembly

Available fully assembled as part #9051




Rear Driveshaft Assembly

Available fully assembled as part #9052



Modular Assembly






Chassis Assembly

This diagram illustrates the exploded view of the chassis assembly, showing the following components and their assembly points:

- Top Components:**
 - 3965 2.5x8 CS (Screws)
 - 2587 3x10 CS (Screws)
 - 6724 (Plastic Mounts/Brackets)
 - 2575 3x6 BCS (Bracket)
 - 2579 3x15 BCS (Bracket)
 - 7477 (Bracket)
 - 1926 (Screw)
 - 1726 (Screw)
 - 3340 (Electronic Speed Control Unit)
- Bottom Components:**
 - 6533 (Electronic Speed Control Unit)
 - 6724 (Plastic Mount/Bracket)
 - 9023 (Bracket)
 - 9022 (Bracket)
 - 9026 (Bracket)
 - 3965 2.5x8 CS (Screws)
 - 2553 3x15 CCS (Bracket)
 - 9023 (Bracket)
 - 3965 2.5x8 CS (Screws)
 - 9026 (Bracket)
- Assembly Points:**
 - Top of the chassis frame
 - Bottom of the chassis frame
 - Electronic Speed Control Unit
 - Various mounting points for brackets and screws

REV 240521-R02



Specifications on this page are subject to change without notice. Every attempt has been made to ensure the accuracy of this drawing; however, Traxxas cannot be held responsible for typographical or other errors.

